16

MATERIAL SAFETY DATA SHEET FOR COATINGS, RESINS AND RELATED MATERIALS (Approved by U.S. Department of Labor 'Essentially Similar' to for form OSHA-20)

MANUFACTURER'S NAME
THE SHERWIN-WILLIAMS COMPANY
101 Prospect Avenue N.W.
Cleveland, Ohio 44115
DATE OF PREPARATION
30-Dec-86

EMERGENCY TELEPHONE NO. (216) 566-2917

INFORMATION TELEPHONE NO. (216) 566-2902

- Trade Mark

Section I -- PRODUCT IDENTIFICATION

PRODUCT NUMBER R7 K 53 PRODUCT NAME

OPEX* Lacquer Etching Thinner

PRODUCT CLASS Reducer

Section II -- HAZARDOUS INGREDIENTS V.P. 64742-89-8 Lt. Aliphatic Hydrocarbon Solvent 64742-48-9 V. M. & P. Naphtha. 108-88-3 Toluene. 1330-20-7 Xylene. 64-17-5 Ethanol 53.0 20 100 500 PPM 12.0 22.0 5.9 44.0 8.7 0.6 12.5 300 100 100 1000 PPM PPM PPM PPM PPM 10 15 5 15 10 45 25 200 100 1000 100 64-17-5 78-83-1 111-76-2 110-19-0

Section III -- PHYSICAL DATA

EVAPORATION RATE -- Slower than Ether VAPOR DENSITY -- Heavier than Air NILING RANGE (F) % VOLATILE VOLUME WT/GAL 172 -- 340 99.7 6.76 6.76 BOILING RANGE (F) 172 - 340 Section IV -- FIRE AND EXPLOSION HAZARD DATA

FLAMMABILITY CLASSIFICATION FLAS
RED LABEL -- Flammable, Flash below 100 F
EXTINGUISHING MEDIA
Carbon Dioxide, Dry Chemical, Foam
UNUSUAL FIRE AND EXPLOSION HAZARDS FLASH POINT 25 F TCC LEL 0.9

UNUSUAL FIRE AND EXPLOSION RAZARDS

Keep containers tightly closed. Isolate from heat, electrical equipment, sparks, and open flame. Closed containers may explode when exposed to extreme heat. Application to hot surfaces requires special precautions. During emergency conditions overexposure to decomposition products may cause a health hazard. Symptoms may not be immediately apparent. Obtain medical attention.

SPECTAL FIRE FIGHTING PROCEDURES

Full protective equipment including self-contained breathing apparatus should be used. Vater spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers to prevent pressure build-up and possible autoignition or explosion when exposed to extreme heat.

OPEX* Lacquer Etching Thinner R7 K 53

Section V -- HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE -- See Section II EFFECTS OF OVEREXPOSURE

PRECENCY OF OVEREXPOSURE

ACUTE: Overexposure causes eye, skin and respiratory irritation. May cause nervous system depression accompanied by headache, dizziness, nausea, confusion and staggering gait. Extreme overexposure may result in unconsciousness and possibly death.

CHRONIC: Prolonged overexposure to ingredients in Section II may cause adverse effects to the liver, urinary, blood forming, cardio-vascular, and reproductive systems. Reports have associated repeated and prolonged overexposure to solvents with permanent brain and nervous system damage.

EMERGENCY AND FIRST AID PROCEDURES

If INHALED: If affected, remove from exposure. Restore breathing. Keep varm and quiet. If on SKIN: Vash affected area thoroughly with soap and water.

Remove contaminated clothing and launder before re-use.

If in EYES: Flush eyes with large amounts of vater for 15 minutes. Get medical attention.

attention.

If SVALLOVED: Never give anything by mouth to an unconscious person. DO NOT INDUCE VOMITING. Give several glasses of vater. Seek medical attention.

Section VI -- REACTIVITY DATA

STABILITY -- Stable
HAZARDOUS DECOMPOSITION PRODUCTS
By fire: Carbon Dioxide, Carbon Monoxide
HAZARDOUS POLYMERIZATION -- Will Not Occur

Section VII -- SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED
Remove all sources of ignition. Ventilate and remove with inert absorbent.
WASTE DISPOSAL METHOD
Waste from this product may be hazardous as defined under the Resource Conservation and
Recovery Act (RCRA) 40 CFR 261. Vaste must be tested for ignitability to determine the
applicable RFA hazardous waste numbers.
Incinerate in approved facility. Do not incinerate closed container. Dispose of in
accordance with Federal, State, and Local regulations regarding pollution.

Section VIII -- PROTECTION INFORMATION

PRECAUTIONS TO BE TAKEN IN USE

Use only with adequate ventilation. Avoid breathing vapor and spray mist. Avoid contact with skin and eyes. Vash hands after using.

VENTILATION

VENTILATION

Local exhaust preferable. General exhaust acceptable if the exposure to materials in Section II is maintained below applicable exposure limits. Refer to OSHA Standards 1910.94, 1910.103.

RESPIRATORY PROTECTION

If personal exposure cannot be controlled below applicable limits by ventilation, wear respiratory device approved by NIOSH/MSHA for protection against materials in Section II.

PROTECTIVE GLOVES

Wear gloves which are recommended by all the controlled below applicable limits by ventilation, wear respiratory device approved by NIOSH/MSHA for protection against materials in Section II.

PROFESTIVE GLOVED

Wear gloves which are recommended by glove supplier for protection against materials in Section II.

Section II.
EYE PROTECTION

Vear safety spectacles with unperforated sideshields.

page 2

Continued on page 2

OPEX* Lacquer Etching Thinner R7 K 53

Section IX -- PRECAUTIONS

DOL STORAGE CATEGORY -- 18

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING
Contents are FLAMMABLE. Keep away from heat, sparks, and open flame.
During use and until all vapors are gone: Keep area ventilated - Do not smoke Extinguish all flames, pilot lights, and heaters - Turn off stoves, electric tools and
appliances, and any other sources of ignition.
Consult NFPA Code. Use approved Bonding and Grounding procedures.
Keep container closed when not in use. Transfer only to approved containers with complete
and appropriate labeling. Do not take internally. Keep out of the reach of children.
OTHER PRECAUTIONS

Intentional misuse by deliberately concentrating and inhaling the contents can be harmful or fatal.

HMIS

1	HEALTH	2
1	FLAMMABILITY	3
1	REACTIVITY	0