MATERIAL SAFETY DATA SHEET FOR COATINGS, RESINS AND RELATED MATERIALS by U.S. Department of Labor 'Essentially Similar' to form OSHA-20)

EMERGENCY TELEPHONE NO. (216) 566-2917

MANUPACTURER'S NAME
THE SHERWIN-WILLIAMS COMPANY
101 Prospect Avenue N.W.
Cleveland, Ohio 44115
DATE OF PREPARATION
15-Dec-86

INFORMATION TELEPHONE NO. (216) 566-2902

Section I -- PRODUCT IDENTIFICATION

PRODUCT NAME
ACTYLIC Enamel Primer
PRODUCT NUMBERS AND COLORS E61 A 60 Gray. E61 R 62 Red Oxide. PRODUCT CLASS
Alkyd Paint

Section II -- HAZARDOUS INGREDIENTS 2.0 7.1 5.9 3.8

Chromium VI (as Cr) 0.3 0.05 Section III -- PHYSICAL DATA

EVAPORATION RATE -- Slower than Ether VAPORATILE VOLUME 63 VAPOR DENSITY -- Heavier than Air UME WT/GAL 10.2 BOILING RANGE (F) 277 - 395

Section IV -- FIRE AND EXPLOSION BAZARD DATA

FLAMMABILITY CLASSIFICATION FLASH POINT 76-80 F PMCC LEL 0.7

RED LABEL -- Flammable, Flash below 100 F

EXTINGUISHING MEDIA

Carbon Dioxide, Dry Chemical, Foam

UNUSUAL FIRE AND EXPLOSION HAZARDS

Keep containers tightly closed. Isolate from heat, electrical equipment, sparks, and open flame. Closed containers may explode when exposed to extreme heat. Application to hot surfaces requires special precautions. During emergency conditions owerexposure to decomposition products may cause a health hazard. Symptoms may not be immediately apparent. Obtain medical attention.

SPECIAL FIRE FIGHTING PROCEDURES

Full protective equipment including self-contained breathing apparatus should be used. Vater spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers to prevent pressure build-up and possible autoignition or explosion when exposed to extreme heat.

Hg/H3

Section V -- HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE -- See Section II

THRESHOLD LIMIT VALUE —— See Section II

EFFECTS OF OVEREXPOSURE

ACUTE: Overexposure causes eye, skin and respiratory irritation. May cause nervous system depression accompanied by headache, dizziness, hausea, confusion and staggering gait. Extreme overexposure may result in unconsciousness and possibly death.

CHRONIC: Studies have associated exposure to Chromium VI compounds with an increased risk of

CHRONIC: Studies have associated exposure to Chromium VI compounds with an increased risk of respiratory cancer.

Prolonged overexposure to ingredients in Section II may cause adverse effects to the liver, wrinary, respiratory, and reproductive systems.

Rats exposed to titanium dioxide dust at 230 mg,/m3 developed lung cancer, however, such exposure levels are not attainable in the workplace.

Reports have associated repeated and prolonged overexposure to solvents with permanent brain and nervous system damage.

EMERGENCY AND FIRST AID PROCEDURES

If INMALED: If affected, remove from exposure. Restore breathing. Keep warm and quiet.

If on SKIN: Vash affected area thoroughly with soap and water.

Remove contaminated clothing and launder before re-use.

If in EYES: Flush eyes with large amounts of water for 15 minutes. Get medical attention.

Section VI -- REACTIVITY DATA

STABILITY -- Stable

HAZARDOUS DECOMPOSITION PRODUCTS

By fire: Carbon Dioxide, Carbon Monoxide, Oxides of Metals in Section II
HAZARDOUS POLYMERIZATION -- Will Not Occur

Section VII -- SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Remove all sources of ignition. Ventilate and remove with inert absorb WASTE DISPOSAL METHOD

WASTE DISPOSAL METHOD

Vaste from this product may be hazardous as defined under the Resource Conservation and
Recovery Act (RCRA) 40 CFR 261. Vaste must be tested for ignitability and extractability to
determine the applicable EPA hazardous waste numbers.

Incinerate in approved facility. Do not incinerate closed container. Dispose of in
accordance with Federal, State, and Local regulations regarding pollution.

Section VIII -- PROTECTION INFORMATION

PRECAUTIONS TO BE TAKEN IN USE

Use only with adequate ventilation. Avoid breathing vapor and spray mist. Avoid contact with skin and eyes. Wash hands after using.

Protect against hazardous dust or fuses which may be generated by sanding, wirebrushing, abrading, burning, brazing or welding of the dried film.

Protect against hazardous dust or tumes which may be generated by sanding, wirebrushing, abrading, burning, brazing or velding of the dried film.
VENTILATION
Local exhaust preferable. General exhaust acceptable if Section II is maintained below applicable exposure limits.
1910.107, 1910.108.
RESPIRATORY PROTECTION

If personal exposure cannot be controlled below applicable limits by ventilation, wear respiratory device approved by NIOSH/MSEA for protection against materials in Section II.

E61 A 60 E61 R 62

Acrylic Enamel Primer

Vear gloves which are recommended by glove supplier for protection against materials in Section II.

EYE PROTECTION

Vear safety spectacles with unperforated sideshields.

Section IX -- PRECAUTIONS

DOL STORAGE CATEGORY -- 1C
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING
Contents are FLAMMABLE. Keep away from heat, sparks, and open flame.
During use and until all vapors are gone: Keep area ventilated - Do not smoke Extinguish all flames, pilot lights, and heaters - Turn off stowes, electric tools and
appliances, and any other sources of ignition.
Consult NFPA Code. Use approved Bonding and Grounding procedures.
Keep container closed when not in use. Transfer only to approved containers with complete
and appropriate labeling. Do not take internally. Keep out of the reach of children.
OTHER PRECAUTIONS

OTHER PRECAUTIONS

This coating contains materials classified as nuisance particulates, for example titanium dioxide, calcium carbonate, etc. (see ACCIM TLV List, Preface and Appendix D), which may be present at hazardous levels only during sanding or abrading of the dried;

Intentional misuse by deliberately concentrating and inhaling the contents can be harmful or fatal.

HMIS

2 * HEALTH 3 FLAMMABILITY 0 REACTIVITY