RATERIAL SAFETY DATA SHEET FOR COATINGS, RESINS AND RELATED MATERIALS (Approved by U.S. Department of Labor 'Essentially Similar' to form OSHA-20)

NUFACTURER'S NAME
THE SHERWIN-WILLIAMS COMPANY
101 Prospect Avenue N.W.
Cleveland, Obio 44115
DATE OF PREPARATION
20-Mar-86

EMERGENCY TELEPHONE NO. (216) 566-2917

INFORMATION TELEPHONE NO. (216) 566-2902

Section I -- PRODUCT IDENTIFICATION

PRODUCT NAME

A-100* Flat Latex House & Trim Paint

PRODUCT NUMBERS AND COLORS A6 A A9 Gunnetal Gray A6 B 550 Tricorn Black A6 G 514 Base C A6 G 514 A6 E A14 A6 E A16 A6 E A17 A6 E A18 A6 L A3 A6 N A3 A6 N 507 White Florida White Bright White Bright White Base B Yellow Corn Yellow Corn Peace Yellow Peace Yellow PRODUCT CLASS

Later Paint

Section II -- HAZARDOUS INGREDIENTS t by NEIGHT ACME-TER 107-21-1 Ethylene Glycol. 0-5

pH - 9.4

Section III -- PHYSICAL DATA

EVAPORATION RATE -- Slower than Ether VAPO LLING RANGE (F) % VOLATILE VOLUME VAPOR DENSITY -- Heavier than Air BOILING RANGE (F) 212 - 388

Section IV -- FIRE AND EXPLOSION HAZARD DATA

FLAMMABILITY CLASSIFICATION

FLASH POINT >199 F PMCC

LEL N.A.

Not Applicable
EXTINGUISHING MEDIA
Carbon Dioxide, Dry Chemical, Alcohol Foam

A6 Series A-100* Flat Latex House & Trim Paint

UNUSUAL FIRE AND EXPLOSION HAZARDS
Extreme heat may cause closed containers
SPECIAL FIRE FIGHTING PROCEDURES

FIRE FIGHTING PROCEDURES
Full protective equipment including self-contained breathing apparatus should be used.
Vater spray may be ineffective. If water is used, fog nommies are preferable. Vater may used to cool closed containers to prevent pressure build-up and possible autoignition or explosion when exposed to extreme heat.

Section V -- HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE -- See Section II EFFECTS OF OVEREXPOSURE

ACUTE: In a confined area vapors in high concentration are anesthetic. Overexposure may result in lightheadedness and staggering gair.

Irritant to skin and upper respiratory system.

EMERGENCY AMD FIRST AID PROCEDURES

If INHALED: If affected, remove from exposure. Restore breathing. Keep warm and quiet.

If on SKIN: Vash affected area thoroughly with soap and water.

Remove contaminated clothing and launder before re-use.

If in EYES: Flush eyes with large memours of water for 15 includes.

If in EYES: Plush eyes with large amounts of water for 15 minutes.

Get medical attention.

Section VI ~~ REACTIVITY DATA

STABILITY -- Stable HAZARDOUS DECOMPOSITION PRODUCTS

By fire: Carbon Dioxide, Carbon Monoxide
HAZARDOUS POLYMERIZATION -- Will Not Occur

Section VII -- SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED
Remove all sources of ignition. Ventilate and remove with inert absorbent.
WASTE DISPOSAL METHOD

WASTE DISPOSAL METHOD

Waste from this product is not hazardous as defined under the Resource Conservation and
Recovery Act (RCRA) 40 CFR 261.

Incinerate in approved facility. Do not incinerate closed container. Dispose of in
accordance with Federal, State, and Local regulations regarding pollution.

Section VIII -- PROTECTION INFORMATION

PRECAUTIONS TO BE TAKEN IN USE

Use only with adequate ventilation. Avoid breathing vapor and spray mist. Avoid contact with skin and eyes. Vash hands after using.

Protect against dust which may be generated by sanding or abrading the dried film.

VENTILATION

VENTILATION

Local exhaust preferable. General exhaust acceptable if the exposure to materials in Section II is maintained below applicable exposure limits. Refer to OSHA Standards 1910.94, 1910.103.

RESPIRATORY PROTECTION

If personal exposure cannot be controlled below applicable limits by ventilation, wear respiratory device approved by NIOSH/MSHA for protection against materials in Section II.

PROTECTIVE GLOVES

Wear gloves which are recommended by glove supplier for protection against materials in Section II.

EYE PROTECTION

Vear safety spectacles with unperforated sideshields.

Continued on page 2

Continued on page 3

page 2

A6 Series A-100* Flat Latex House & Trim Paint Section IX -- PRECAUTIONS

DOL STORAGE CATEGORY -- 38
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING
Keep container closed when not in use. Transfer only to approved containers with complete and appropriate labeling. Do not take internally. Keep out of the reach of children.
OTHER PRECAUTIONS

OTHER PRECAUTIONS

This coating contains materials classified as nuisance particulates, for example titanium dioxide, calcium carbonate, etc. (see ACGIH TLV List, Preface and Appendix D), which may be present at hazardous levels only during sanding or abrading of the dried f

This Material Safety Data Sheet conforms to the Bazard Communication standard, 29 CPR 1910.1200(g)(4), for similar complex mixtures.

The above information pertains to this product as currently formulated, and is based on the information available at this time. Addition of reducers or other additives to this product may substantially siter the composition and hazards of the product. Since conditions of use are outside our control, we make no warranties, express or implied, and assume no liability in connection with any use of this information.